

Section 5.4. Three Dimensional Applications

Note. We now take supports from 2 dimensions to 2 dimensions. We consider:

1. Ball and socket supports,
2. roller supports,
3. hinges,
4. bearings, and
5. built-in supports.

See Table 5.2 for the corresponding reactions.

Example. Page 249 Number 5.87.

Revised: 9/26/2018