6.3. The Method of Sections

1

Section 6.3. The Method of Sections

Definition. A section of a truss is part of the truss obtained by cutting the original

truss.

Note. In the method of sections, we try to find the axial forces in specific members.

We prefer to cut at most three members so that we have three equations in three

unknowns.

Example. Page 289 Number 6.39(a).

Revised: 9/26/2018